

ONCORE TECHNICAL APPLICATION NOTE

UT Plus Production Firmware Version 3.2

Several changes to the UT Plus firmware have been made based on customer inputs since the released 3.1 version. This note documents the changes between UT Plus firmware version 3.1 and firmware version 3.2.

1. 100PPS Correction - 100PPS corrected to prevent a pulse train slip of 1 msec at every skew time.
2. 1PPS Pulse Placement - Calculations were modified to account for oscillator movement.
3. Default year changed to 1/1/2000.

